

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	09/20/2016 09/20/2016	Herman Phillips

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD2060_01_f_2014_4				
Comment Code					
Inspector Comment					
RD 2060 has the O&M Manual on file.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD2060_01_f_2014_7				
Comment Code					
Inspector Comment					
RD 2060 has emergency supplies on hand.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	09/20/2016 09/20/2016	Herman Phillips

LM Start		Rating **	A	Issue No.	12
LM End		Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD2060_01_s_2012_12				
Comment Code					
Inspector Comment					
RD 2060 has trained staff for a flood fight.					

No Photos

LM Start	0.00	Rating **	M	Issue No.	5
LM End	5.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.247342°	38.263293°	
			-121.696283°	-121.771557°	
DWR ID	DWR_RD2060_01_f_2016_5				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Landside levee slope has been sprayed, sprayed grasses has not been removed from slope.					

Photo 1 of 1 : FA\_2016\_RD2060\_241\_5\_20160920\_00006.jpg



RD 2060 Landside slope looking downstream from levee mile 0.00.

LM Start	0.19	Rating **	M	Issue No.	8
LM End	5.08	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.247467°	38.263293°	
			-121.699638°	-121.771557°	
DWR ID	DWR_RD2060_01_f_2016_8				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Sprayed weeds has not been taken off levee section. Remove the small oak trees in area while they are still small.					

No Photos

**\* Location**

LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.97	09/20/2016 09/20/2016	Herman Phillips

LM Start	1.82	Rating **	C	Issue No.	13
LM End	1.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.256048°	38.256048°
				-121.724303°	-121.724303°
DWR ID	DWR_RD2060_01_s_2016_13				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Repairs are needed to this site. Need rock.					

No Photos

LM Start	5.08	Rating **	M	Issue No.	6
LM End	5.08	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Repair Gates			38.263157°	38.263157°
				-121.771543°	-121.771543°
DWR ID	DWR_RD2060_01_s_2012_6				
Comment Code					
Inspector Comment					

No Photos

**\* Location**  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Ulatis Creek	Right	3.64	09/20/2016 09/20/2016	Herman Phillips

LM Start	0.01	Rating **	A	Issue No.	8
LM End	3.64	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.275082 °	38.296645 °
				-121.794938 °	-121.748772 °
DWR ID	DWR_RD2060_02_f_2016_8				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
There are no unwanted weeds or vegetation on the levee section both waterside and landside.					

Photo 1 of 1 : FA\_2016\_RD2060\_242\_8\_20160920\_00010.jpg



Looking downstream from levee mile 0.01 Unit 2 RD 2060.

LM Start	0.05	Rating **	A	Issue No.	10
LM End	3.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.275510 °	38.296645 °
				-121.795298 °	-121.748772 °
DWR ID	DWR_RD2060_02_f_2016_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Ulatis Creek	Right	3.64	09/20/2016 09/20/2016	Herman Phillips

LM Start	<b>3.54</b>	Rating **	M	Issue No.	<b>9</b>
LM End	<b>3.61</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.296370°	38.296730°	
			-121.750608°	-121.749303°	
DWR ID	DWR_RD2060_02_s_2016_9				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	09/20/2016 09/20/2016	Herman Phillips

LM Start	0.01	Rating **	A	Issue No.	13
LM End	3.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.296638 °	38.267223 °
				-121.748655 °	-121.702818 °
DWR ID	DWR_RD2060_03_f_2016_13				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
No unwanted vegetation on the levee slopes.					

Photo 1 of 1 : FA\_2016\_RD2060\_243\_13\_20160920\_00016.jpg



RD 2060 Looking downstream from levee mile 0.01 waterside slope.

LM Start	0.01	Rating **	A	Issue No.	14
LM End	3.54	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.296638 °	38.266833 °
				-121.748655 °	-121.702338 °
DWR ID	DWR_RD2060_03_f_2016_14				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	09/20/2016 09/20/2016	Herman Phillips

LM Start	1.52	Rating **	M	Issue No.	8
LM End	1.74	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.288598°	38.286051°
				-121.725184°	-121.722818°
DWR ID	DWR_RD2060_03_s_2016_8				
Comment Code					
Inspector Comment					
Site added in 1997 and removed in 2003. 2005 - Put back in the inventory. 2006 - Stone repair at the middle of the site. 2011 - Some rock place at toe in the past year. 2013 - Site extended both upstream and downstream to include new erosion pockets. 2015: No observed changes. [2015 Site ID: CHS_23-6_R]					

Photo 1 of 1 : FA\_2016\_RD2060\_243\_8\_20160913\_00007.jpg



USACE 2013 Photo #1

LM Start	2.02	Rating **	M	Issue No.	1
LM End	2.08	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.284105 °	38.283302 °
				-121.718471 °	-121.717814 °
DWR ID	DWR_RD2060_03_s_2016_1				
Comment Code					
Inspector Comment					
2010 - Small maintenance site. 2015: No observed changes. [2015 Site ID: CHS_23-0_R]					

Photo 1 of 1 : FA\_2016\_RD2060\_243\_1\_20160913\_00001.jpg



USACE 2013 Photo #1

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	09/20/2016 09/20/2016	Herman Phillips

LM Start	2.18	Rating **	M	Issue No.	7
LM End	2.23	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.282100 °	38.281510 °
				-121.716817 °	-121.716319 °
DWR ID	DWR_RD2060_03_s_2016_7				
Comment Code					
Inspector Comment					
2007 - Geotechnical failure of midside slope and wave wash/scalloping in toe area. Stone revetment upstream and downstream of site. Similar sites are present all along the right bank downstream of this site, most could be repaired with some maintenance. 2010 - Minor new erosion. 2015: No observed changes. [2015 Site ID: CHS_22-8_R]					

Photo 1 of 1 : FA\_2016\_RD2060\_243\_7\_20160913\_00006.jpg



USACE 2013 Photo #1

LM Start	2.35	Rating **	M	Issue No.	4
LM End	2.53	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.280377 °	38.278306 °
				-121.714633 °	-121.712722 °
DWR ID	DWR_RD2060_03_s_2016_4				
Comment Code					
Inspector Comment					
2008 - Small scour pockets and mid-slope wave wash. 2010 - More vegetation growth, could be fixed through maintenance. 2011 - Site extended downstream and new erosion. 2015: No observed changes. [2015 Site ID: CHS_22-6_R]					

Photo 1 of 1 : FA\_2016\_RD2060\_243\_4\_20160913\_00003.jpg



USACE 2013 Photo #1

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2060 Hastings

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	09/20/2016 09/20/2016	Herman Phillips

LM Start	2.55	Rating **	M	Issue No.	5
LM End	2.58	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.278145°	38.277774°
				-121.712609°	-121.712137°
DWR ID	DWR_RD2060_03_s_2016_5				
Comment Code					
Inspector Comment					
2013 - Erosion pockets into the levee toe. 2015: Erosion pockets have increased in size. [2015 Site ID: CHS_22-5_R]					

Photo 1 of 1 : FA\_2016\_RD2060\_243\_5\_20160913\_00004.jpg



USACE 2013 Photo #1

LM Start	2.79	Rating **	M	Issue No.	6
LM End	2.79	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.275302°	38.275302°
				-121.710130°	-121.710127°
DWR ID	DWR_RD2060_03_s_2016_6				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : FA\_2016\_RD2060\_243\_6\_20160913\_00005.jpg



USACE 2013 Photo #1

LM Start	3.17	Rating **	A/W	Issue No.	12
LM End	3.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.270863 °	38.270324 °
				-121.706800 °	-121.705904 °
DWR ID	DWR_RD2060_03_s_2012_12				
Comment Code					
V8 : Environmental Requirements.					
Inspector Comment					
There was a fire this spring that burned this revegetation site, during the 2012 inspection new growth has sprouted up. During the 2013 inspection new sprouts continue to come up.					

No Photos

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	09/20/2016 09/20/2016	Herman Phillips

LM Start	3.58	Rating **	M	Issue No.	15
LM End	4.47	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.266490 °	38.255363 °
				-121.701802 °	-121.694725 °
DWR ID	DWR_RD2060_03_f_2016_15				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Control the vegetation on the waterside slope between levee mile 3.58-4.47,other wise everything else looks good.					

No Photos

LM Start	3.78	Rating **	M	Issue No.	2
LM End	4.09	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.264585 °	38.260593 °
				-121.698868 °	-121.696403 °
DWR ID	DWR_RD2060_03_s_2016_2				
Comment Code					
Inspector Comment					
2011 - Several pockets of erosion from rotational failure and slumping toe. 2013 - Site extended downstream to include new erosion pockets. 2015: No observed changes. [2015 Site ID: CHS_21-1_R]					

Photo 1 of 1 : FA\_2016\_RD2060\_243\_2\_20160913\_00002.jpg



USACE 2013 Photo #1

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---